	$\bigcup$
Superfund Site Strategy Recommendation	Region 6
Site Name: <u>El Reno Roundhouse Area</u> Si	te Number: <u>OKD 987073475</u> 3
Alias Site Name(s): <u>Rock Island Line</u>	
Address: North of El reno on the east	side of US HWY 81
City/County or Parish/State/Zip: <u>El Ro</u>	eno/Canadian/OK/73036
Recommendation:	
1. No further remedial action plan	nned under Superfund.
xx 2. Further pre-remedial investigations Superfund:	tive action needed under
PA	Priority: High
SSI_xx	Medium_XX
LSI	
Other	
To be performed by	•
3. Action may be appropriate unde	er other authority:

SPCC

SMCRA

Discussion: PA

NPDES\_ UIC

DTHER

The El Reno railyard being investigated in this report is the former roundhouse site where heavy maintenance likely occurred. The soil may be contaminated with heavy metals in the paint shed area and there is a tar pit which may contain spent solvents, waste oils and coal tars from washing railcars and engine maintenance. Also located on site are several disposal pits and wastewater lagoons. This site has existed for 100 years or more, and past historical uses are speculative. Stressed vegetation and possible spill areas are visible both on the ground and in aerial photos. estimates there is a minimum of 800 to 1000 cubic yards of waste soil. There are no restrictions to the site, and evidence indicated juveniles had been on the property. Ground water can be as shallow as 5 feet in the area and the is potential for contamination of the local aquifer. There are numerous targets who use local wells for drinking. Because of the potential danger to ground water and also on-site contamination further investigation of this site is recommended in the form of UPERFOND FILE

404

STATE

TSCA

RCRA

JUN 0 4 1992

		REORGANIZED			
Copies to (please list) ATSDR, 6W-S, 6E-E,	OSDH		,	,	
Recommended By: Babasa Dustell	Date:	08	/30	Ro	<b>~</b>
Approved By: Bill Jowa	Date:	8	31	191	920113
		1		1"	